

## PURCHASE REQUEST

City Government of Davao

LGU

PR-Contt-46

Section		oor 5, iviagsa	SAI No.: Da ALOBS No.: Da	ate:	
Item		Unit of	ALODS No Da	Estimated	Datiment
No.	Quantity	Issue	Items Description	Unit Cost	Estimate Cost
1	1	LOT	Cat. 06 – AUTO REPAIR SHOP		
	1	LOI	Repair and Replacement of service Vehicles		60,224
			remove replace tie rod end rl / lh(outer, inner) - 2 sides		
	AL.		remove replace velocity boots (outer) - 2 sides		
			remove replace valve cover gasket		
			remove replace rh tail light bulb 1 side		
			remove repair power window (driver side) 1 side		
			remove replace tail light rh - 1 side		
			remove stall & fix gear box assy.,		
			General cleaning (air-con) w/ flashing charging leak test		
			remove replace fit man arm		
			complete wheel alignment		
			Wash over labor & materials		
	1		straighten/ alighn rh/lh step board & rhs siding panel -2 sides		
			remove repair front bumper panel & rear bumper		
EGO	TIATE	-n	Tie rod end (inner/outer) - 1 Set		
		-1	velocity boots (outer) @ 550/pc - 2 pcs	-	
OCL	REM		valve cover gasket 1 pc		
-	- 1		Bulb 12v single 1 pc	at a second	
all V	LUE PR	/	Tail light rhs 1 pc		
		9-020	,		
o me	s.No.	0-000	This is to certify that the items above are included		
2016	_date	823	in the APP of this office under pages 1 & 2.		
			Certificel(Correct:		
	L. DUTE	RTE			
CITY N	IAYUK	8.	* PARTY		
			ATTY. MARLON S. CASOURJO	1	
			DIRECTOR III/Election Officer IV, 1st District		
urpose	Vehicle s	ervice repa	air S GRAND TOTA	T -	60.224
Requeste	The same of the sa	ATT	VATRISTANIOVI GREEN MIDGO		60,224.
				rippio	ved by.
rinted N	Atty.	Marlon S. Ca	squejo (Attininistration) Acting Asst. City Treasurer - Oprn	SARA 7.	DUTERTE
agiana	Director I	II/Election	Officer IV 16-018310 - 760, 224.80/8h	City	The state of the s

Name & Signature of controller:

Date:

ATTY, Marlon S. Casquejo

ATTY. TRISTAL DWAGNED D MINGO Assistant City Administrator (Administration)